5/25

Split A

DART AEROSPACE LTD	Work Order:	23340 A
Description: Wearplate	Part Number:	D3319-1
Dwg: D3319 Rev. A page 1	Qty:	30 Y
72/2		Page 1 of 1

Step	Location	Procedure	By	Date	Qty
1	DC	Issue Traveler	HA	65.06.13	30
2	PG	Email or Ship DXF file to vendor Laser Cut flat pattern per Dwg D3319 Possible Supplier: Industrial Laser Material release note is required	A	05/10/11	30
3	RG	Receive and inspect for transit damage Ensure material release note is attached	CL	05/10/25	31
4	QC6	Inspect dimensions as per inspection template D3319-1T1	1/2	05-11-16	30
5	GA	Deburr if necessary		NA	
6	GB	Form using DT8326 & DT8261 as per Dwg D3319 Dwg Rev:	53	05/11/17	30
7	GB	Form flat on press using DT8776 block Dwg Rev:	SB	05/11/17	30
8	QC6	Inspect dimensions as per Dwg D3319	M	05/4/23	30
9	WS	Weld hard surface using D3319-1T2 as per QSI 004 and Dwg D3319 Outy Part Number Description M/9(00 Batch A/R N/A Description M/9(00 Batch T560 Hardcoat Rod Description M/9(00 Batch T560 Hardcoat Rod	PL	05-(12	4
10	QC9	Inspect weld	PD	05-112	34
11	FP	Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3	M	05.11.24	4
12	QC3	Inspect Powder Coat	SB	05/11/24	4
13	ST	Identify on inside surface using a permanent fine point marker with the following: TCCA-PDA, Dart Aerospace Ltd. P/N: D3319-1, B/N: BXXXXX For Product Eligibility see PDA04-18 and Stock	C.L. SB	105/11/20 X	4
14	AC	Cost / part:	Sut	05-11-24	4
15	DC	Close W/O inspect Level 21	B	05/11/24	14

Rev	Date	Change	Revised By	Approved
Α	05.05.12	New issue	KJ/JLM (111

PRELIMINARY ISSUE